



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200

D3272-1
Job Sheet 169952



Part No: D3272-1

Job Qty: 5 ea

Part Name: Step



Part Weight: 0 lbs

Status: Scheduled

Priority: Medium

Job Created: 1/4/18

Job Tracking No:

Due Date: 1/12/18

Created By: Mario Poulin

Type: SOLD

Description:

Note: DWG REV B IPP Rev:A New Issue 07-06-09 JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	5 Ea		1/11/18	0.00	0.00	Start Up Large Fab-4		DC 2018-01-12
100	Large Fab	5 pcs		1/12/18	0.00	2.33	Large Fab 8		DC 2018-01-12
110	QC	5 pcs		1/12/18	0.00	0.00	QC5		CPC
120	Packaging	5 pcs		1/12/18	0.00	0.00	Packaging3 Large Fab		CPC
130	QC21-SA	5 Ea		1/12/18	0.00	0.00	QC21		

Part Op 100 - ***SQUARE ONE END BEFORE CUTTING OTHER END*** 1-Cut D2622-120 extrusion to 116.25" long as per Dwg
Descriptions: D3272 using cutting table setup DT 8185-2A 2-Drill extrusion as per Dwg D3272 using Jig DT8680 for rivets. 3-Deburr
120 - LOCATION: WA003

Job Allocations

Operation	Component Part	Required	Inventory	Allocated	Std Qty
90-Start up Operation	D2622-120C 162484-2	5	84	0	0

DART
AEROSPACE
S031748



Step

Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

lin.mario

PART NO: D3272-1
Revision:
Operation: Start up Operation
Change No:

Mfg Date: 01/12/18
Job No: 169952

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER :					